

(C2) Craft SLEP 60-Ton Portal Crane Mandatory Alterations

Mandatory Number	Classification	Date Issued	Title
N3258A-C2-010A	When-Needed	8/24/23	Alteration of Phase Sequence Monitor Relay Circuit
N3258A-C2-015	When-Needed	5/10/23	Alteration of OEM Drive and PLC Parameters for Tuning Crane Functions
N3258A-C2-014	Delayed-B	5/10/23	Alteration of Potentiometer Tunable Variables to PLC
N3258A-C2-013	When-Needed	5/2/23	Alteration of Main Hoist HPU Solenoid Connectors
N3258A-C2-012	When-Needed	9/22/22	Alteration Main Hoist and Whip Hoist Drive Parameters
N3258A-C2-011	When-Needed	9/1/22	Documentation (AS-BUILT VARIANCE) of Whip Hoist BSDS Brake Linings
N3258A-C2-010	When-Needed	5/24/22	Alteration of Phase Sequence Monitor Relay Circuit
N3258A-C2-009	When-Needed	5/3/22	Installation and adjustment of the Modified Boom Pawl Actuator Assembly
N3258A-C2-008	Delayed-B	4/28/22	Alteration of PLC and Transformer Fusing
N3258A-C2-007A	When-Needed	4/8/22	Replacement of Whip Hoist Wire Rope
N3258A-C2-007	When-Needed	4/5/22	Replacement of Whip Hoist Wire Rope
N3258A-C2-006	Delayed-B	3/7/22	Software Changes Required to Correct Various Issues Identified via Warrant Request and During Commissioning/Field Test
N3258A-C2-005	Delayed-B	10/1/21	Replacement of Hoist Dynamic Braking Contactors
N3258A-C2-004	Delayed-B	7/20/21	Software Changes Required to Increase Operator Control of the Rotate Function
N3258A-C2-003	When-Needed	10/28/20	Alteration of Control Power Circuit
N3258A-C2-002	Delayed	9/27/19	Alteration of Rotate Tachloss Software
N3258A-C2-001	Delayed - B	3/11/19	Alteration to LMI Software