

(C2) Craft SLEP 60-Ton Portal Crane Mandatory Alterations			
Mandatory Number	Classification	Date Issued	Title
N3258A-C2-018	Delayed - A	6/2/25	Addition of Drive Logic to Detect Conflicting Commands
N3258A-C2-017	Delayed - B	6/2/25	Replacement of CAT 6 Cables
N3258A-C2-016	Delayed - B	10/18/24	Replacement of Auxiliary Power Transfer Switch & Alteration to Transfer Switch Supply Source Indicator Lights
N3258A-C2-010A	When-Needed	8/24/23	Alteration of Phase Sequence Monitor Relay Circuit
N3258A-C2-015	When-Needed	5/10/2023	Alteration of OEM Drive and PLC Parameters for Tuning Crane Functions
N3258A-C2-014	Delayed - B	5/10/2023	Alteration of Potentiometer Tunable Variables to PLC
N3258A-C2-013	When-Needed	5/2/2023	Alteration of Main Hoist HPU Solenoid Connectors
N3258A-C2-012	When-Needed	9/22/22	Alteration Main Hoist and Whip Hoist Drive Parameters
N3258A-C2-011	When-Needed	9/1/22	Documentation (AS-BUILT VARIANCE) of Whip Hoist BSDS Brake Linings
N3258A-C2-010	When-Needed	5/24/22	Alteration of Phase Sequence Monitor Relay Circuit
N3258A-C2-009	When-Needed	5/3/2022	Installation and adjustment of the Modified Boom Pawl Actuator Assembly
N3258A-C2-008	Delayed - B	4/28/2022	Alteration of PLC and Transformer Fusing
N3258A-C2-007A	When-Needed	4/8/2022	Replacement of Whip Hoist Wire Rope
N3258A-C2-007	When-Needed	4/5/2022	Replacement of Whip Hoist Wire Rope
N3258A-C2-006	Delayed - B	3/7/2022	Software Changes Required to Correct Various Issues Identified via Warrant Request and During Commissioning/Field Test
N3258A-C2-005	Delayed - B	10/1/2021	Replacement of Hoist Dynamic Braking Contactors
N3258A-C2-004	Delayed - B	7/20/2021	Software Changes Required to Increase Operator Control of the Rotate Function
N3258A-C2-003	When-Needed	10/28/2020	Alteration of Control Power Circuit
N3258A-C2-002	Delayed	9/27/2019	Alteration of Rotate Tachloss Software
N3258A-C2-001	Delayed - B	3/11/2019	Alteration to LMI Software