

**(W1) Westmont 100-Ton Floating Crane Mandatory Alterations**

<b>Mandatory Number</b>	<b>Classification</b>	<b>Date Issued</b>	<b>Title</b>
N3258A-W1-017	When Needed	20-Sep-21	Replacement of Boom Hoist Wire Rope
N3258A-W1-016	Delayed - C	5-Feb-21	Alteration of Boom Pawl Circuit
N3258A-W1-015	When Needed	3-Nov-20	Upgrade Hydraulic Pumps
N3258A-W1-014	When Needed	6-Feb-18	Replacement of Whip and Aux Hoist Motors
N3258A-W1-013	When Needed	20-Aug-15	Replacement of LMI System
N3258A-W1-012	Delayed - B	20-Aug-15	Modification of the Boom Pawl Electrical Circuit
N3258A-W1-011	When Needed	20-Aug-15	Whip and Aux Hoist Drum LeBus Grooved Sleeves
N3258A-W1-010A	Delayed - B	21-Mar-11	Addition of hoist limit switches to deisel stop circuit
N3258A-W1-010	Delayed - B	20-Jan-11	Addition of hoist limit switches to deisel stop circuit
N3258A-W1-009	Delayed - B	24-Jun-10	Replacement of DC control power circuit breaker
N3258A-W1-008	When Needed	27-Aug-07	Replacement of function master switches
N3258A-W1-007	Delayed - B	23-Jul-07	Documentation (as-built variance) of secondary upper limit bypass
N3258A-W1-006	When Needed	18-Jan-07	Alteration of hydraulic cooling fan control circuit
N3258A-W1-005A	Delayed - B	8-Mar-06	Alteration of hoist limit switches
N3258A-W1-004C	Delayed - A	19-May-05	Motor mounting flange cap screw failure
N3258A-W1-004B	Delayed - A	14-Dec-04	Motor mounting flange cap screw failure
N3258A-W1-005	Delayed - B	3-Nov-03	Alteration of hoist limit switches
N3258A-W1-004A	Delayed - B	24-Oct-02	Motor mounting flange cap screw failure
N3258A-W1-004	Delayed - B	11-Oct-02	Motor mounting flange cap screw failure
N3258A-W1-003	When Needed	26-Feb-01	Addition of collector ring brush holder arm limiter
N62472-W1-002A	Delayed - Bearing Replacement	9-Dec-99	Repair overstressed member in machinery deck
N62472-W1-002	Delayed - Bearing Replacement	8-Apr-99	Repair overstressed member in machinery deck
N62472-W1-001A	Delayed - B	22-Mar-99	Repl main diesel engine single element housing fuel filter
N62472-W1-001	Delayed - B	20-Apr-98	Repl main diesel engine single element housing fuel filter